OWNER

The U.S. Government. Operated by the U.S. Army Corps of Engineers, Fort Worth District.

ENGINEER (Design)

U.S. Army Corps of Engineers.

LOCATION

On the Bosque River in McLennan County, 2 miles west of Waco.

DRAINAGE AREA

1,670 square miles.

DAM

Earthfill with concrete spillway Type Length 24,618 ft Maximum height 140 ft Top width 20 ft

SPILLWAY

Type Ogee Length (net) 560.0 ft

Crest elevation 465.0 ft above msl

Control 14 tainter gates, each 40 by 35 ft

OUTLET WORKS

Type 1 conduit, 20 ft diameter 400.0 ft above ms! Control 3 gates, each 6 ft 8 in. by 20 ft

AUTHORIZATION

Federal: Flood Control Act, September 3, 1954.

Permit No. 1115 (Application No. 1187) August 15, 1929, to the city of Waco with authority to impound 39,000 acre-feet of water in the old reservoir with

annual diversion of 85,000 acre-feet. This amount was reduced to 40,000 acre-feet by order of the State Board of Water Engineers October 13, 1960.

Permit No. 1931 (Application No. 2082) June 6, 1957, allows the 39,000 acre-feet to be stored in the new reservoir.

Permit No. 1930 (Application No. 2081) March 9, 1960, to the city of Waco changing former allocations to 104,100 acre-feet storage and annual diversion to 59,100 acre-feet. Brazos River Authority has purchased 91,000 acre-feet of storage capacity in the reservoir for \$6,000,000.

RESERVOIR DATA

FEATURE	ELEVATION (FEET ABOVE MSL)	CAPACITY (ACRE-FEET)	AREA (ACRES)
Top of dam	510.0	_	
Maximum design water surface	505.0	828.300	21 200
Top of flood control storage space	500.0	726,400	21,390 19,440
Spillway crest	465.0	233,500	9,220
Top of conservation storage space	455.0	152.500	7,270
Streambed	370.0	-	7,270
Maximum tailwater	431.6	_	_
Sediment reserve below	455.0	48.400	
Sediment reserve above	455.0	20.600	_
Usable conservation storage space	_	104.100	_

GENERAL

Construction started June 13, 1958 Impoundment of water began February 26, 1965 Dam completed June 24, 1965

General contractor Earthwork: Clement Bros., Hickory North Carolina

Spillway: Elmer Gardner

Repairs: R. G. LaTourneau, Inc.

Estimated cost \$49,407,000

Difficulty was encountered in construction due to a foundation condition that caused sliding and damage to the embankment. This required a change in plans with additional volume of materials and another contract for completion.

